				)					
	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	ErrorDefinition	Er ro rs
1	BRS	L 1	5834	microfluidic\$5 or microchannel\$1	USPA T; EPO; JPO; DERW, ENT	2002/12/0 1 22:01			0
2	BRS	L 6	1600 870	silicon quartz glass	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:01	)		0
3	BRS	L 1 1	2571 53	vent\$3	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:02			0
4	BRS	L 1 6	1322 86	hydrophobic\$5	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:02			О
5	BRS	L 2 1	2575 76	(gas\$3 or air) near5 (inlet\$3 or intak3 or input\$4)	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:09	0		0
6	BRS	L 2 6	25	1 and 6 and 11 and 16 and 21	USPA T; EPO; JPO; DERW ENT	2002/12/ 1 22:25	0		0

		•							
	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errordefinition	Errors
7	BRS	L 3 1	1	16 and 6048734.pn.	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:08			0
8	BRS	L 3 6	0	31 and 21	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:08			0
9	BRS	L 4 1	1	16 and 6057149.pn.	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:09			0
10	BRS	L 4 6	0	(31 41) and 11	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:09			0
11	BRS	L 5 1	2	(gas\$3 or air) and (31 41)	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:09			0
12	BRS	L 5 6	525	1 and 6 and 16	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 22:26			0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	Enrordefinition	
13	BRS	L 6 1	226	(435/\$.ccls. or 436/\$.ccls. or 422/\$.ccls.) and 56		2002/12/0 1 22:56			0
14	BRS	L 6 6	1	61 and 5637469.pn.		2002/12/0 1 22:56			0
15		L 7 1	1	66 and etch\$3		2002/12/0 1 23:06			0
16		L 7 6	1	66 and etch\$3 and vent\$3	USPA T; EPO; JPO; DERW ENT	2002/12/0 1 23:10			0
17	BRS	L 8 1	1	66 and etch\$3 and (air or gas\$3)		2002/12/0 1 23:11			0